



检测报告

152512050049

TEST REPORT

报告编号

YNZKBG20230727037-3

Report No

项目名称

大理丰顺医疗废物处置有限公司 2023 年第三季度比对监测

Name

委托单位

大理丰顺医疗废物处置有限公司

Client

项目地址

大理州大理市下关镇吊草村大风坝垃圾处理场以西

Address

样品类别

空气和废气

Type

编制:

Compiled by

李雪燕

校核:

Proofread check

张玉兰

审核:

Inspected by

马江

签发:

Approved by

签发日期:

2023 年 07 月 27 日

Approved Date

Y M D

云南中科检测技术有限公司

Yunnan Sino-sci Testing Tech. Co, LTD

报告日期

2023 年 07 月 27 日

Report Date

Y M D

声 明

Introduction

1.报告无“CMA 资质认定章”和检测单位“检测专用章”及“骑缝章”无效。

This report no seal on the perforation and CMA qualification certification seal and special seal for testing is invalid.

2.报告无编制人、审核人、签发人签名无效，报告经涂改无效。

This report without prepare people signature, audit staff signature, approver signature is invalid, The report by alter is invalid.

3.报告未经本机构批准，不得复制（全文复制除外）本报告或证书。

This report or certificate can't be copied (except in full) without the approval of the agency .

4.对委托人送检的样品进行检测的，检测报告对样品所检项目的符合性情况负责，送样样品的代表性和真实性由委托人负责；除委托方特别声明并支付样品管理费以外，所有样品超过标准或技术规范要求的时效性均不再留样。

If the sample submitted by the client is tested, the test report shall be responsible for the conformity of the items tested by the sample, and the client shall be responsible for the representativeness and authenticity of the sample submitted; Unless the entrusting party makes a special statement and pays the sample management fee, the timeliness of all samples exceeding the requirements of standards or technical specifications will not be retained.

5.委托方应对提供的检测相关信息的完整性、真实性、准确性负责。本公司实施的所有检测行为以及提供的相关报告以委托方提供的信息为前提，当委托方提供的信息可能影响结果的有效性时，本公司不承担由此引起的任何责任。

The entrusting party shall be responsible for the completeness, authenticity and accuracy of the testing related information provided. All testing behaviors and related reports provided by our company are based on the information provided by the entrusting party. When the information provided by the entrusting party may affect the effectiveness of the results, our company will not assume any responsibilities arising therefrom.

6.报告未经检测单位同意不得用于广告，商品宣传等商业行为。

This report without the consent of the testing organization shall not be used for advertising, advertising products such as business practices.

7.委托方如对本检测报告有任何异议，请于收到报告之日起十五日内向本公司提出申请，逾期不申请的，视为认可本检测报告。

If the client has any objection to the test report, please apply to the company within 15 days from the date of receiving the report. If the client fails to apply within the time limit, it shall be deemed to have approved the test report.

地 址： 云南省昆明经济技术开发区云大西路 39 号新兴产业孵化区 3 幢 3 层厂房
Address: The 3-story factory Building, 3 Building, Emerging Industry Incubation Zone,
No.39 Yunda West Road, Kunming Economic and Technological Development
Zone, Yunnan Province.

邮 编： 650500

Postcode ID:

电 话： 0871-63852008

Telephone No:

传 真： 0871-63802005

Fax No:

网 址： www.sttynzk.com

Website:

1.检测信息

表 1 检测信息

客户基本情况										
委托单位信息	单位名称	大理丰顺医疗废物处置有限公司								
	通讯地址	大理州大理市下关镇吊草村大风坝垃圾处理场以西								
	联系人	姚燮林	联系电话	13987202591						
受检单位信息	单位名称	大理丰顺医疗废物处置有限公司								
	通讯地址	大理州大理市下关镇吊草村大风坝垃圾处理场以西								
	联系人	姚燮林	联系电话	13987202591						
样品基本情况										
样品类别	样品名称	采样点位	采样频次		采样人员	采样时间	收样时间	收样人员	分析时间	样品状态描述
			天数	次/天						
空气和废气	有组织 排放废气	A5：焚烧炉烟囱排气口	1	9	王卫高 李海棋	2023.07.14	2023.07.15	杨 婷 杨海南	2023.07.15- 2023.07.17	——

2.生产工单编号、检测类别、项目、方法、设备

表 2 检测分析方法及主要仪器设备一览表

生产工单编号	样品类别	检测项目	检测方法	检测和分析设备	仪器编号	分析人员	检出限/ 测定下限		
YNZKSC 20230710003	空气和废气	颗粒物	HJ 836-2017 固定污染源废气 低浓度颗粒物的测定 重量法	ESJ30-5B 电子天平	YNZK-FX106	杨婷	1.0mg/m³		
				ZR-3260 自动烟尘烟气综合测试仪	YNZK-XC179				
				二氧化硫	HJ 57-2017 固定污染源废气 二氧化硫的测定 定电位电解法	ZR-3260 自动烟尘烟气综合测试仪	YNZK-XC179	王卫高 李海棋	3mg/m³
		氮氧化物	HJ 693-2014 固定污染源废气 氮氧化物的测定 定电位电解法						3mg/m³
		氯化氢	HJ 549-2016 环境空气和废气 氯化氢的测定 离子色谱法	CIC-100 离子色谱仪	YNZK-FX065	普红青	0.2mg/m³		
				ZR-3260 自动烟尘烟气综合测试仪	YNZK-XC179				
				ZR-3710 双路烟气采样器	YNZK-XC433				

3.检测结果

表 3 有组织排放废气检测结果表

检测项目	采样点位	采样日期	样品编号	排气筒 高度 (m)	烟气参数						检测结果	
					流速 (m/s)	烟温 (°C)	静压 (kPa)	含湿量 (%)	含氧量 (%)	标干流量 (m³/h)	实测浓度 (mg/m³)	
											NO.1	
颗粒物	A5: 焚烧炉烟囱 排口	2023.07.14	YNZKSC 20230710003-A139	35	5.6	119.4	-0.08	17.91	13.6	4354	17.8	
			YNZKSC 20230710003-A140		6.5	122.5	-0.09	17.45	13.2	5041	15.4	
			YNZKSC 20230710003-A141		6.6	124.6	-0.06	18.02	13.1	5059	19.3	
			YNZKSC 20230710003-A142		7.2	127.2	-0.07	17.68	12.7	5505	19.0	
			YNZKSC 20230710003-A143		7.4	127.3	-0.08	18.22	12.3	5619	17.7	
			YNZKSC 20230710003-A144		7.1	124.4	-0.07	17.34	11.6	5489	18.2	
			YNZKSC 20230710003-A145		7.0	123.7	-0.07	18.15	11.7	5368	18.4	
			YNZKSC 20230710003-A146		7.6	125.5	-0.09	18.32	13.1	5789	17.9	
			YNZKSC 20230710003-A147		6.2	124.8	-0.06	17.82	13.5	4761	18.1	
			平均值		6.8	124.4	-0.07	17.88	12.8	5221	18.0	

NO.2

检测项目	采样点位	采样日期	样品编号	排气筒高度 (m)	烟气参数						检测结果
					流速 (m/s)	烟温 (℃)	静压 (kPa)	含湿量 (%)	含氧量 (%)	标干流量 (m³/h)	实测浓度 (mg/m³)
二氧化硫	A5：焚烧炉烟囱 排口	2023.07.14	YNZKSC 20230710003-A139	35	5.6	119.4	-0.08	17.91	13.6	4354	47
			YNZKSC 20230710003-A140		6.5	122.5	-0.09	17.45	13.2	5041	53
			YNZKSC 20230710003-A141		6.6	124.6	-0.06	18.02	13.1	5059	68
			YNZKSC 20230710003-A142		7.2	127.2	-0.07	17.68	12.7	5505	70
			YNZKSC 20230710003-A143		7.4	127.3	-0.08	18.22	12.3	5619	66
			YNZKSC 20230710003-A144		7.1	124.4	-0.07	17.34	11.6	5489	95
			YNZKSC 20230710003-A145		7.0	123.7	-0.07	18.15	11.7	5368	61
			YNZKSC 20230710003-A146		7.6	125.5	-0.09	18.32	13.1	5789	45
			YNZKSC 20230710003-A147		6.2	124.8	-0.06	17.82	13.5	4761	50
			平均值		6.8	124.4	-0.07	17.88	12.8	5221	62

NO.3

检测项目	采样点位	采样日期	样品编号	排气筒 高度 (m)	烟气参数						检测结果
					流速 (m/s)	烟温 (℃)	静压 (kPa)	含湿量 (%)	含氧量 (%)	标干流量 (m³/h)	实测浓度 (mg/m³)
氮氧化物	A5：焚烧炉烟囱 排口	2023.07.14	YNZKSC 20230710003-A139	35	5.6	119.4	-0.08	17.91	13.6	4354	255
			YNZKSC 20230710003-A140		6.5	122.5	-0.09	17.45	13.2	5041	258
			YNZKSC 20230710003-A141		6.6	124.6	-0.06	18.02	13.1	5059	262
			YNZKSC 20230710003-A142		7.2	127.2	-0.07	17.68	12.7	5505	268
			YNZKSC 20230710003-A143		7.4	127.3	-0.08	18.22	12.3	5619	292
			YNZKSC 20230710003-A144		7.1	124.4	-0.07	17.34	11.6	5489	227
			YNZKSC 20230710003-A145		7.0	123.7	-0.07	18.15	11.7	5368	287
			YNZKSC 20230710003-A146		7.6	125.5	-0.09	18.32	13.1	5789	197
			YNZKSC 20230710003-A147		6.2	124.8	-0.06	17.82	13.5	4761	209
			平均值		6.8	124.4	-0.07	17.88	12.8	5221	251

NO.4

检测项目	采样点位	采样日期	样品编号	排气筒高度 (m)	烟气参数						检测结果
					流速 (m/s)	烟温 (℃)	静压 (kPa)	含湿量 (%)	含氧量 (%)	标干流量 (m³/h)	实测浓度 (mg/m³)
一氧化碳	A5：焚烧炉烟囱 排口	2023.07.14	YNZKSC 20230710003-A139	35	5.6	119.4	-0.08	17.91	13.6	4354	11
			YNZKSC 20230710003-A140		6.5	122.5	-0.09	17.45	13.2	5041	11
			YNZKSC 20230710003-A141		6.6	124.6	-0.06	18.02	13.1	5059	11
			YNZKSC 20230710003-A142		7.2	127.2	-0.07	17.68	12.7	5505	11
			YNZKSC 20230710003-A143		7.4	127.3	-0.08	18.22	12.3	5619	10
			YNZKSC 20230710003-A144		7.1	124.4	-0.07	17.34	11.6	5489	11
			YNZKSC 20230710003-A145		7.0	123.7	-0.07	18.15	11.7	5368	12
			YNZKSC 20230710003-A146		7.6	125.5	-0.09	18.32	13.1	5789	11
			YNZKSC 20230710003-A147		6.2	124.8	-0.06	17.82	13.5	4761	11
			平均值		6.8	124.4	-0.07	17.88	12.8	5221	11

NO.5

检测项目	采样点位	采样日期	样品编号	排气筒 高度 (m)	烟气参数						检测结果
					流速 (m/s)	烟温 (℃)	静压 (kPa)	含湿量 (%)	含氧量 (%)	标干流量 (m³/h)	实测浓度 (mg/m³)
氯化氢	A5：焚烧炉烟囱 排口	2023.07.14	YNZKSC 20230710003-A130	35	5.6	119.4	-0.08	17.91	13.6	4354	3.20
			YNZKSC 20230710003-A131		6.5	122.5	-0.09	17.45	13.2	5041	3.30
			YNZKSC 20230710003-A132		6.6	124.6	-0.06	18.02	13.1	5059	3.38
			YNZKSC 20230710003-A133		7.2	127.2	-0.07	17.68	12.7	5505	3.62
			YNZKSC 20230710003-A134		7.4	127.3	-0.08	18.22	12.3	5619	3.34
			YNZKSC 20230710003-A135		7.1	124.4	-0.07	17.34	11.6	5489	3.12
			YNZKSC 20230710003-A136		7.0	123.7	-0.07	18.15	11.7	5368	3.34
			YNZKSC 20230710003-A137		7.6	125.5	-0.09	18.32	13.1	5789	3.64
			YNZKSC 20230710003-A138		6.2	124.8	-0.06	17.82	13.5	4761	3.50
			平均值		6.8	124.4	-0.07	17.88	12.8	5221	3.38

报告结束

报告编号: YNZKBG20230727037-3
ReportNo

附图:

大理丰顺医疗废物处置有限公司 2023 年第三季度比对监测点位图

